Overdue Inspections List With All Contacts

Results by:	HW~SH; Order Re	Use: JSK~PB~PB/ł	rizona; Status: Active; l		•		•	ss 1: ;City:		eria: NOB/	
	on ID: 989824	Locatio					Miami		n Order by: Ad		Location Na
1 object(s)		Phone:									Address:
, , ,	NOB/SIC:			FIPS:				Gila	Gi	County:	
			-3658	- Cell: (928) 701	28) 473-7241	Phone: (92	spector -	nservice Ins	eith Taylor, In	ontact: Ke	Primary Co
										ntact:	Billing Con
	658	- Cell: (928) 701-3	Phone: (928) 473-7241	ool, AZ 85532 - I	Street Clayp	5701 New	spector -	nservice Ins	eith Taylor, In	ict: Ke	Cert Conta
										ntact:	Owner Con
us Location	Due Date Status	Schedule Type	Year Insurer	<u>Manufacturer</u>	<u>Serial</u>	At <u>NB</u>	SV Set A	MAWF	<u>Use</u>	Type	<u>Jur#</u>
ve Caustic unloading	02/04/2019 Active	Internal Cert	2016 State of Arizona	Lattner Boiler Co	96619	57674	30	125	PB	FT	AZ021411
v _	02/04/2019 Activ	Internal Cert	2016 State of Arizona	Lattner Boiler Co	96619	57674	30	125	PB		AZ021411

TOTAL OBJECTS 1 TOTAL LOCATIONS 1